

Reports from Navigating Ships about drifting matters (October 2011)

Date and Time	Point		Kind of drifting matters	Features of drifting matters (※ Please inform us about information which is not only size, but also others which help us to find the drifting matters as minutely as possible)			Status (※ Upright/ Quarter Submerged/ Half Submerged/ Three Quarters Submerged/ Entirely Submerged/ Capsized/ etc.)		
	latitude	longitude		Size (Length), Weight	Color	ship name, registration number, etc.	Status	Height from the surface of the sea	Other information
10 : 46 , Oct. 21th , 2011	38 ° 0 ' 0 " N	144 ° 8 ' 18 " E	A lumber (part of a ladder)	2m	-		Half Submerged		
5 : 10 , Oct. 21th , 2011	37 ° 50 ' 40 " N	144 ° 49 ' 42 " E	A log (a raw timber)	6m	-		Half Submerged		having a root which is about 2m length
14 : 22 , Oct. 22th , 2011	37 ° 0 ' 0 " N	143 ° 49 ' 28 " E	A lumber	1m			Half Submerged		
14 : 38 , Oct. 22th , 2011	37 ° 0 ' 0 " N	143 ° 52 ' 36 " E	Fishing gear (a buoy, rope, hampers etc.)	2m ²	buoy:black, rope:white		Half Submerged	30cm	see Picture ①
7 : 7 , Oct. 23th , 2011	37 ° 7 ' 7 " N	144 ° 0 ' 38 " E	Logs (raw timbers)	6m			Half Submerged		see Picture ②
8 : 8 , Oct. 23th , 2011	37 ° 8 ' 30 " N	143 ° 47 ' 24 " E	A log (a fitting)	3m		50cm across	Half Submerged		see Picture ③
8 : 30 , Oct. 23th , 2011	37 ° 9 ' 0 " N	143 ° 43 ' 0 " E	A hamper	1m			Half Submerged		
14 : 59 , Oct. 23th , 2011	37 ° 19 ' 0 " N	142 ° 18 ' 30 " E	A lumber (a fitting)	3m			Half Submerged		see Picture ④
11 : 28 , Oct. 27th , 2011	39 ° 35 ' 18 " N	145 ° 43 ' 48 " E	A log	15m			Half Submerged		
8 : 15 , Oct. 30th , 2011	35 ° 28 ' 12 " N	146 ° 59 ' 54 " E	A drum	φ800mm×1200mm	red		Three Quarters Submerged	200mm	see Picture ⑤
15 : 17 , Oct. 31th , 2011	38 ° 0 ' 0 " N	145 ° 51 ' 42 " E	A log	6m			Half Submerged		see Picture ⑥

Pictures of marine debris from ships (October 2011)

Picture ① Fishing gear (a buoy, rope, hampers etc.)



date and time 2011/10/22 14:38
point 37-00-00N, 143-52-36E
notes

Picture ② Logs (raw timbers)



date and time 2011/10/23 7:07
point 37-07-00N, 144-00-38E
notes

Picture ③ A log (a fitting)



date and time 2011/10/23 8:08
point 37-08-30N, 143-47-24E
notes

Picture ④ A lumber (a fitting)



date and time 2011/10/23 14:59
point 37-19-00N, 142-18-30E
notes

Picture ⑤ A drum



date and time 2011/10/30 8:15
point 35-28-12N, 146-59-54E
notes

Picture ⑥ A log



date and time 2011/10/31 15:17
point 38-00-00N, 145-51-42E
notes