

Reports from Navigating Ships about drifting matters (November 2011)

Date and Time	Point		Kind of drifting matters	Features of drifting matters (※ Please inform us about information which is not only size, but also others which help us to find the drifting matters as minutely as possible)			Status (※ Upright/ Quarter Submarged/ Half Submarged/ Three Quarters Submarged/ Entirely Submarged/ Capsized/ etc.)		
	latitude	longitude		Size (Length), Weight	Color	ship name, registration number, etc.	Status	Height from the surface of the sea	Other information
3 : 5 , Nov. 1st , 2011	33 ° 55 ' 6 " N	155 ° 55 ' 42 " E	Plenty fishing net and buoy	about 10m square	fishing nets: black buoys: orange/black	-	Half Submarged	about 0.2m	about 30 pcs of fishing buoy and net were assembled in 10m square
9 : 45 , Nov. 2nd , 2011	39 ° 6 ' 42 " N	171 ° 5 ' 36 " E	A fishing boat	About 15 m L 4m B	white	registration number: MG3 40582 (Not clear; painted on Port side)	Uplight	3m	having a Japanese name see Picture ①
12 : 11 , Nov. 4th , 2011	38 ° 14 ' 48 " N	141 ° 36 ' 35 " E	A log	3m			Half Submarged		see Picture ②
12 : 40 , Nov. 4th , 2011	38 ° 21 ' 18 " N	141 ° 39 ' 2 " E	A log	2m			Half Submarged	30cm	see Picture ③
13 : 20 , Nov. 4th , 2011	38 ° 29 ' 55 " N	141 ° 42 ' 30 " E	A log	2m			Half Submarged		see Picture ④
9 : 28 , Nov. 5th , 2011	38 ° 45 ' 1 " N	144 ° 34 ' 12 " E	A drum	2m			Half Submarged		see Picture ⑤
12 : 38 , Nov. 6th , 2011	38 ° 40 ' 0 " N	143 ° 47 ' 18 " E	A fender	2m	black		Quater Submarged	1m	see Picture ⑥
12 : 55 , Nov. 10th , 2011	37 ° 25 ' 0 " N	141 ° 50 ' 0 " E	A net with floats	φ 2~3m	green, red		Half Submarged		see Picture ⑦
14 : 5 , Nov. 11th , 2011	37 ° 0 ' 0 " N	142 ° 29 ' 54 " E	A pail made of plastic	1m across 1m high	yellow		Half Submarged		see Picture ⑧
15 : 47 , Nov. 11th , 2011	37 ° 0 ' 0 " N	142 ° 40 ' 2 " E	A gas cylinder	50cm across 150cm long	rust		Half Submarged		see Picture ⑨
1 : 1 , Nov. 18th , 2011	43 ° 47 ' 59 " N	172 ° 11 ' 37 " E	A small boat	about 12m L	red (bottom)	made of wood	Capsized	1m	
12 : 30 , Nov. 21th , 2011	34 ° 5 ' 0 " N	175 ° 8 ' 0 " E	A fishing vessel	about 5t	white (body) blue (bottom)		Capsized	1m	tidal current: 270° velocity: 0.5nott/h wind: ESE, 5m/s weather: cloudy atmospheric pressure: 1028mb see Picture ⑩

## Pictures of marine debris from ships (November 2011)

Picture ① A fishing boat



date and time  
point  
notes

2011/11/2 9:45  
39-06-42N, 171-05-36E

Picture ② A log



date and time 2011/11/4 12:11  
point 38-14-48N, 141-36-35E  
notes

Picture ③ A log



date and time 2011/11/4 12:40  
point 38-21-18N, 141-39-02E  
notes

Picture ④ A log



date and time 2011/11/4 13:20  
point 38-29-55N, 141-42-30E  
notes

Picture ⑤ A drum



date and time 2011/11/5 9:28  
point 38-45-01N, 144-34-12E  
notes

Picture ⑥ A fender



date and time 2011/11/6 12:38  
point 38-40-00N, 143-47-18E  
notes

Picture ⑦ A net with floats



date and time 2011/11/10 12:55  
point 37-25-00N, 141-50-00E  
notes

Picture ⑧ A pail made of plastic



date and time 2011/11/11 14:05  
point 37-00-00N, 142-29-54E  
notes

Picture ⑨ A gas cylinder



date and time 2011/11/11 15:47  
point 37-00-00N, 142-40-02E  
notes

Picture ⑩ A fishing vessel



date and time 2011/11/21 12:30  
point 34-05-00N, 175-08-00E  
notes